Y0999-198 ncfeely



OUT TO REACTOR (carrier gas + source gas)




FIGURE 1

LACE SUBSTRATE 2002

IN REACTOR

WITH ATTACHED BUBBLER

EVACUATE REACTOR

HEAT SURSTRATE TO

REACTION TEMPERATURE

PLOW CAPRIER 6AS
THROUGH BUBBLER INTO
REACTION CHAMBER
TO EFFECT DEFORTION

STOP CARRIER GAS FLOW EVACUATE CHAMBER

TO ROOM TEMP

VENT REACTOR,
REMOVE FINISHED PART

FIGURE 2